EVALUATION OF SIDEWALK CONDITIONS WITHIN MAGOTHY FOREST

SEVERNA PARK, MD

B. BIDDLE, P.E.

MAGOTHY F	OREST
-----------	-------

SIDEWALK EVALUATION **EXISTING CONDITIONS** COVER PAGE


BAB

SCALE

NONE

DRAWN BY DATE DEC. 2020

PLAN NO SW-0A



Address	Red	Blue	Green	Sheet
250 Whistling Pine Road			17.0	SW-02
257 Whistling Pine Road			16.6	SW-06
132 Wild Oak Road	43.9			SW-08A
134 Wild Oak Road	49.6			SW-09
136 Wild Oak Road	15.7			SW-10
138 Wild Oak Road	15.2	78.0		SW-11
142 Wild Oak Road		127.2		SW-13
144 Wild Oak Road		62.5	31.3	SW-14A
144 Wild Oak Road		46.9	46.9	SW-14B
287 Wilderness Road	107.2			SW-15
289 Wilderness Road		16.3		SW-16
291 Wilderness Road	171.7			SW-17
293 Wilderness Road			16.4	SW-18
295 Wilderness Road	16.0			SW-19A
220 Lower Magothy Beach Road	59.3			SW-20
214 Lower Magothy Beach Road		65.2	32.6	SW-22
210 Lower Magothy Beach Road		33.7		SW-24
289 Whistling Pine Road	68.1			SW-25A
285 Whistling Pine Road	48.7		15.7	SW-27
283 Whistling Pine Road			17.0	SW-28
281 Whistling Pine Road		93.1		SW-29
277 Whistling Pine Road		33.7		SW-30
275 Whistling Pine Road		63.6		SW-32
133 Wild Oak Road	54.4			SW-34
SUBTOTALS	649.8	620.2	193.5	

MAGOTHY FOREST

SIDEWALK EVALUATION EXISTING CONDITIONS SUMMARY OF QUANTITIES

DATE	DRAWN BY	SCALE	PL
DEC. 2020	BAB	1"=10'	

PLAN NO. SW-0C

